
PCN 250926 - GNS 5892R MPN change

confidential information notification

INTRODUCTION

Due to clerical mistake wrong EAN Code part has been created in ERP system, existing part number will be replaced by correct EAN code part number.

Production of GNS5892R V12 (MPN–4037735104784) will be discontinued. Instead, the successor Product GNS5892R V13 (MPN–4037735107038) will be Produced.

LIST OF CHANGES MADE

Old MPN- 4037735104784

New MPN- 4037735107038

COMPATIBILITY

There will be no impact on functionality and geometry of module because of this change.

TIME SCHEDULE

From the date of publication of this PCN document, distribution of GNS5892R V12 (MPN–4037735104784) will be replaced by GNS5892R V13 (MPN–4037735107038).

DATASHEET REVISION

A new revision of the datasheet is available: ***GNS5892R_datasheet_V13.pdf***

THE INFORMATION IN THIS DOCUMENTATION DOES NOT FORM ANY QUOTATION OR CONTRACT. TECHNICAL DATA ARE DUE TO BE CHANGED WITHOUT NOTICE.

NO LIABILITY WILL BE ACCEPTED BY THE PUBLISHER FOR ANY CONSEQUENCE OF THIS DOCUMENT'S USE.

REPRODUCTION IN WHOLE OR IN PART IS PROHIBITED WITHOUT THE PRIOR WRITTEN CONSENT OF THE COPYRIGHT OWNER